

Classroom Committee Type III/IV Room Renovation Information Sheet, Spring 1998

Bldg/Rm	Cap	Seats	% of Tech. Rooms in Building	Technology Use/Comments									Utilization Factor			
				97-98 ytd			96-97			95-96			Fall 97	Fall 96	Fall 95	Fall 94
				computer	slides	video	computer	slides	computer	computer	slides	video				
BH 003	76	T-A	3%	6	5	95	1	19	79	6	13	46	.51	.58	.55	.46
BH 005	60	Fixed	3%	2	6	39	2	5	68	0	10	75	1.31	.73	.68	.47
BH 006	60	Fixed	3%	1	3	36	0	3	107	2	33	132	.63	.84	.79	.77
BH 103	87	T-A	3%	0	40	60	22	14	76	0	31	133	.34	.38	.34	.35
BH 109	143	Fixed	3%	ATA. Lighting is marginal.									.41	.43	.40	.39
BH 204	80	T-A	3%	64	27	60	1	20	112	1	13	160	.41	.40	.36	.36
BH 304	70	T-A	3%	4	7	171	4	2	174	15	5	131	.46	.46	.41	.45
BH 310	144	Fixed	3%	4	73	125	1	112	109	2	27	93	.42	.47	.45	.38
BH 330	82	T-A	3%	2	14	138	1	0	192	0	80	227	.50	.39	.36	.50
BH 347	84	T-A	3%	0	2	34	5	9	97	26	39	156	.52	.59	.54	.56
EP 220	165	Fixed	100%	ATA. General room renovation.									.42	.39	.40	.44
FA 015	245	Fixed	25%	2	booth	104	2	booth	73	0	booth	117	.55	.46	.49	.44
				Room has been made ADA accessible; new carpet, walls. Still needs infrastructure for technology and better lights and control.												
JH 239	110	T-A	14%	0	1	8	0	2	16	0	4	23	.90	.54	.51	.42
				Equipment also provided by Biology.												
OP 105	146	Fixed	66%	ATA. General room renovation.									.40	.39	.39	.43
SW 007	148	Fixed	12%	3	0	87	0	0	31	1	2	91	.50	.47	.43	.50
				Equipment also provided by Physics and Astronomy.												
SW 119	232	Fixed	12%	ATA. Lighting and control are poor. Faculty complaints.									.29	.39	.36	.32
WH 100	417	Fixed	7%	MTC. Lighting and control are poor. Teacher station not ADA accessible.									.40	.48	.45	.28
WH 101	169	Fixed	7%	MTC. Lighting and control are poor. Teacher station not ADA accessible. Faculty complaints.									.29	.27	.25	.28